

APPENDIX - VIII


PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE.


No. 798

Date: 16/11/21

It is certified that an inspection team headed by ASHOK MUKATI  
Assistant Engineer PHE Sub Dn Damoh (Name of Officers  
with designation) from P.H.E. Sub Dn Damoh (Name of  
Department/Office) inspected the Maharshi Vidhya Mandir  
Sr. Sec. School Ladanbag P. Hathna Damoh (Name & Address of  
the School) on 12/11/21 and found that the Maharshi  
Vidhya Mandir Sr. Sec. School (Name of school) has safe  
drinking water facilities for the students and members of staff of the institution and is maintaining  
the hygienic sanitation condition in the school building & the campus as per the norms  
prescribed by the Central/State/U.T Govt.

The above valid for a period of 15/11/2022 (for 1 year)

  
Assistant Engineer  
P.H.E. Sub Division  
Damoh  
Labh

Signature with Seal:   
Executive Engineer  
P.H.E. Dn. DAMOH  
Name: SHRI M.K. Umariya  
Designation: EEPHE Dn Damoh

To

MAHARISHI VIDYA  
MANDIR SR. SEC. SCHOOL LADANBAG  
POST HATHNA DAMOH (M.P.)

(Name & Address of the Institution)